

Mitre GTILT PLUS output dated 06-17-2017 at 13:03:01 Inclinator SD02A
File C:\nervi\SD02a.gtl



License 3P9746W
Client
Project
Location
Stickup m

Summary of Flagged Readings:-

| Date | Start Time | End Time | Water Level | Probe No. | Cable No. | Reader No. | Start Volts | End Volts |
|----------|------------|----------|-------------|-----------|-----------|------------|-------------|-----------|
| 06152017 | 0441 | | | 10G | | | | |

SD02 set 1, read 15 Jun 2017:-

| Depth | A0 | A180 | B0 | B180 | Sum A | Sum B |
|-------|------|------|------|------|-------|-------|
| 0.5 | -129 | 138 | -19 | -11 | 9 | -30 |
| 1.0 | -142 | 142 | -41 | 17 | 0 | -24 |
| 1.5 | -164 | 164 | -61 | 54 | 0 | -7 |
| 2.0 | -164 | 169 | -80 | 76 | 5 | -4 |
| 2.5 | -184 | 196 | -111 | 105 | 12 | -6 |
| 3.0 | -263 | 254 | -87 | 85 | -9 | -2 |
| 3.5 | -230 | 233 | -26 | -10 | 3 | -36 |
| 4.0 | -270 | 274 | -107 | 102 | 4 | -5 |
| 4.5 | -291 | 295 | -76 | 68 | 4 | -8 |
| 5.0 | -307 | 309 | -55 | 47 | 2 | -8 |
| 5.5 | -297 | 296 | 53 | -63 | -1 | -10 |
| 6.0 | -212 | 218 | 40 | -52 | 6 | -12 |
| 6.5 | -210 | 208 | -17 | -12 | -2 | -29 |
| 7.0 | -216 | 217 | -35 | 8 | 1 | -27 |
| 7.5 | -278 | 284 | -49 | 39 | 6 | -10 |
| 8.0 | -336 | 339 | -63 | 58 | 3 | -5 |
| 8.5 | -349 | 347 | -217 | 208 | -2 | -9 |
| 9.0 | -386 | 392 | -349 | 343 | 6 | -6 |
| 9.5 | -440 | 439 | -259 | 255 | -1 | -4 |
| 10.0 | -454 | 453 | -235 | 230 | -1 | -5 |
| 10.5 | -454 | 459 | -231 | 223 | 5 | -8 |
| 11.0 | -470 | 473 | -184 | 179 | 3 | -5 |



, Inclinometer SD02B